

# Pilkington

Rossford, Ohio

**6F3 Furnace Rebuild:**

Pilkington announced their plans to rebuild 6F3 Furnace in Rossford, Ohio with production to begin production in 1999. The rebuilt furnace will manufacture flat glass. Since 1826 Pilkington has manufactured top quality glass. They continue to grow and develop their product worldwide.

**Scope of Work:**

IPS is responsible for the installation of cooling water lines, compressed air, natural gas piping, combustion air piping, oxygen piping, hydrogen, nitrogen, helium, oxygen and instrumentation of the 6F3 Furnace Rebuild at the Rossford, Ohio facility.

*Project Facts*

Project Duration  
6 Months

Total Project Cost  
\$3.5 Million

MANUFACTURING

For more information about IPS, visit us at  
[www.IPScontractor.com](http://www.IPScontractor.com)



**IPS**